



G3 Extra Plus System Process Chart

For Medium Solids Paint Systems

Stage 1: CUT

G3 Extra Plus
Abrasive Compound

1 Stage 1: CUT

Product Size
1kg

Codes
G3E124

Applicators

G Mop 6" High Cut Foam	GMC618
G Mop 8" High Cut Foam	GMC818
G Mop 3" Yellow Compounding Foam	GMC312
G Mop 6" Yellow Compounding Foam	GMC612
G Mop 8" Yellow Compounding Foam	GMC812

- ATTACH**
Attach a G Mop foam to a polishing machine
- SHAKE**
Shake bottle well before use
- POUR**
Dispense a small quantity of product onto surface or pad
- 1000 - 1300rpm**
Compound at 1900 - 1300rpm
- FC-3 (3 x cloths)**
Wipe clean with a Finishing Cloth FC-3 (3 x cloths)

Stage 2: FINISH

G3 Fine
Finishing Compound

2 Stage 2: FINISH

Product Size
500g
1kg
1 US gallon

Codes
G3F501
G3F101
G3F118

Applicators

G Mop 3" Finishing Foam	GMF301
G Mop 6" Finishing Foam	GMF601
G Mop 8" Finishing Foam	GMF801

- ATTACH**
Attach a G Mop Finishing Foam to a polishing machine
- SHAKE**
Shake bottle well before use
- POUR**
Dispense a small quantity of product onto surface or pad
- 1000rpm**
Spread and start compounding at 1000rpm
- 2000rpm**
Slowly increase speed to 2000rpm. **DO NOT ALLOW PRODUCT TO DRY**
- FC-3 (3 x cloths)**
Wipe clean with a Finishing Cloth FC-3 (3 x cloths)

Stage 3: PROTECT

G3 Glaze
Gloss Enhancer

3 Stage 3: PROTECT

Product Size
500ml
1ltr
1 US gallon

Codes
G3G501
G3G101
G3G118

G3 Wax
Premium Liquid Protection

Product Size
500ml
1ltr
1 US gallon

Codes
G3W501
G3W106
G3W118

Applicators for both products

G Mop 3" Finishing Foam	GMF301
G Mop 6" Finishing Foam	GMF601
G Mop 8" Finishing Foam	GMF801

Finishing Cloth (3 x cloths) **FC-3**

Stage 3: PROTECT - G3 Glaze (for fresh paint)

- ATTACH**
Attach a G Mop Back Plate and a G Mop Finishing Foam to a polisher
- SHAKE**
Shake bottle well and apply a small quantity to the pad
- 800 - 1100rpm**
Polish at 800 - 1100rpm
- FC-3 (3 x cloths)**
Wipe clean with a Finishing Cloth FC-3 (3 x cloths)

Stage 3: PROTECT - G3 Wax (for fully cured paint)

- SHAKE**
Shake bottle well and apply a small quantity to the surface or cloth
- FC-3 (3 x cloths)**
Rub the product in a circular motion onto the surface
- haze**
Allow to dry to a haze
- FC-3 (3 x cloths)**
Wipe clean with a Finishing Cloth FC-3 (3 x cloths)

Remove Defect

Inspect defect

Remove defect - P1500



G3 Extra Plus TECHNICAL BENEFITS

ON ALL MS & HS PAINTS

- Good cut & excellent gloss
- Permanent scratch remover from P1500
- Clean and economical
- Low swirls



WYATT MACHINE TOOLS

New Zealand's Leading Collision Repair Experts

www.wyatt.co.nz

388 Church St, Penrose, Auckland

info@wyatt.co.nz

Ph: 09 525 1000